



MUNICIPAL CORPORATION OF DELHI
OFFICE OF THE EXECUTIVE ENGINEER [M SHAH(N)]-II
C-12, YAMUNA VIHAR, DELHI-110053



No. E.E.-[M Shah(N)]-II/2023-24/...65...

Dated...18/4/2024

To

The Manager

GYAN SAROVER BAL VIDYALAYA

Ganwari Marginal Bandh, Delhi-110053

SUBJECT:- SCHOOL BUILDING FITNESS CERTIFICATE.

In reference to your letter No GSBC/2024/155 dated 08.04.2024 on the above cited subject, this is to certify GYAN SAROVER BAL VIDYALAYA, Ganwari Marginal Bandh, Delhi-110053, has been inspected by the concerned Junior Engineer from safety point of view of building and found satisfactory condition at present.

As per visual inspection of the building, it seems that the condition of building is satisfactory for running the school as also reported by the structural engineer M/s Architechno Combine Copy attached with this application for obtaining the fitness certificate.

This certificate is valid for one year

ASSTT. ENGINEER
M-II SHAH(NORTH)
Asstt. Engineer
Maint Div-II Sh. (N) Zone
Municipal Corporation of Delhi-53